


<b>A.x1</b>	<b>B.x1</b>	<b>C.x1</b>	<b>D.x1</b>	<b>E.x1</b> carré 20x20	<b>F.x1</b> ø25
<b>G.x1</b>	<b>I.x2</b>	<b>K.x1</b>	<b>L.x1</b> ø20	<b>M.x2</b>	<b>N.x2</b>
<b>H.x1</b>					
<b>O.x2</b> ø20	<b>P.x8</b> ø25	<b>Q.x2</b> ø30	<b>R.x1</b> 35x15	<b>S.x3</b> 40x40	<b>T.x1</b> ø20 int.
<b>W.x1</b>	<b>X.x1</b>	<b>Y.x2</b>	<b>Z.x1</b>	<b>AA.x1</b>	<b>AB.x8</b> ø8xø30
<b>AE.x4</b> 35 mm	<b>AF.x1</b> 60 mm	<b>AG.x2</b> 20 mm	<b>AH.x4</b> 60 mm	<b>AI.x2</b> M3	<b>AJ.x5</b> M6
					<b>AK.x6</b> M8

Fig. 1



Echelle pour les vis 0 10 20 30 40 50 60mm

Fig. 2




Fig. 4




Fig. 6




Fig. 3




Fig. 5





Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12

